


+B = 320V
 +B1 = 310V
 +B2 = 305V



To bias points 6V - 16V